

Measure H Bond Program

Issue Number 4



West Elementary School Underground Utility Repair

The Facilities Team is performing an assessment of the West Elementary School under-ground utilities. As part of the Measure H bond program, the team will be repairing underground utilities that are in poor repair at West. The team is meeting with civil engineering groups and contractors to review the options for repairing the utilities at West Elementary School.

A Pod Remodel

We are thrilled to share an exciting update regarding South School's A Pod. After careful consideration and collaboration with the design team, we have selected a new flooring material, style, and color scheme that we believe will enhance the overall look and feel of the school. The new flooring material is durable and low maintenance, ensuring that it can withstand the daily wear and tear of a bustling school environment. The style of the flooring is modern and sleek, which will give the school a fresh and updated appearance. Additionally, the color scheme has been thoughtfully chosen to complement the existing décor and create a cohesive aesthetic throughout the school.

New Colors at North!

The community was invited to review and provide feedback on the color options on display at North School. After tallying the votes, the community mostly favored color palette #2, as it received over 80% of the votes. This palette features a Brickhouse Tan Body, Amber Slate Trim, Windows, a Ramp Structure, and various colors for doors. The community's valuable feedback will now be conveyed to the design team, who will work on finalizing the new color palette for North School. Seeing the community come together and actively participate in this decision-making process. This exterior paint project is slated to take place alongside South School's exterior paint project this summer.